


392.50



1. ALL PANELS TO BE CUT FROM SHEET SUCH THAT THE METAL GRAIN RUNS HORIZONTALLY.
2. PANELS MUST BE SHEARED FROM THE SAME SIDE.
3. EDGES MUST BE CLEAN AND FREE FROM BURRS OR TOOL WITNESSES.
4. PANEL FACES MUST BE SCRATCH FREE.
5. HANDLE WITH CARE DURING MANUFACTURE.
6. PANELS ARE TO SUPPLIED WRAPPED IN PROTECTIVE PAPER.

A4