


A
—
B
—
C
—
D
—
E
—
F
—
G
—
H
—
I



General tolerances ± 0.20
Resultant tolerances between
hole centers ± 0.15
Tolerances on hole diameters ± 0.05
Angles $\pm 0.5^\circ$
Surface finish $\sqrt{32}$

A2

SS